

# HDD/SSD Support

	HDD SATA	HDD SAS	SSD	Mixing	Sun Flash Module	LSI HBA mix supported *	Intel/Adaptec HBA mix supported *	REM
M3000		4						
M4000		2						
M5000		4						
M8000		16						
M9000-32		32						
M9000-64		64						
T1000	1	2						
T2000		2						
T5120		8	4 **	x			x	
T5140		8	4 **	x			x	
T5220		16	8 **	x			x	
T5240		16	8 **	x			x	
T5440		4	4 **	x				
X2250	2							
X2270	4		4	x	2			
X4140		8	4	x		x	x	
X4150		8	4 on board	x		x	x	
X4170	8 ***	8 ***	4 ***	only SSD/SAS or SSD/SATA		x	x	
X4240		16	8	x		x	x	
X4250		16				x	x	
X4270		16 ***	8 ***	no SSD/SATA mix				
X4275	12 ***	12 ***	8 ***	no SSD/SATA mix		no SSD support	x	
X4440		8	4	x		x	x	
X4450		8 ***	4 onboard ***	x		x	x	
X4600		4						
T6340	2	2	2	only SSD/SAS or SSD/SATA				x ****
T6320	4	4	4	only SSD/SAS or SSD/SATA				x ****

T6300	4	4					
X6450			1		1		
X6440					1		
X6275					2		
X6270		4 ****	4 ****		1		
X6250	4 ****	4 ****	4 ****		1		
X6240	4 ****	4 ****	4 ****		1		

- \* Mixing of SSD with SAS or SATA drives
- \*\* SATA SSD support requires LSI firmware version 1.27.00.00 or better
- \*\*\* SAS HDDs, SATA HDDs and SATA SSDs cannot be mixed within the same RAID volume
- \*\*\*\* RAID volumes must not mix SSDs and HDDs
- \*\*\*\*\* no mixing of SSDs and HDDs